


**MPI™ UNION CONNECTOR**

**SERIES HBMP7**



| Part No.    | MPI™ Size (in.) | A (in.) | D (in.) | W Hex (in.) | Working Pressure (PSIG) |
|-------------|-----------------|---------|---------|-------------|-------------------------|
| 4-4 HBMP7   | 1/4             | 2.88    | 1.88    | 5/8         | 15,000                  |
| 6-4 HBMP7   | 3/8 - 1/4       | 3.32    | 2.19    | 3/4         | 15,000                  |
| 6-6 HBMP7   | 3/8             | 3.44    | 2.19    | 3/4         | 15,000                  |
| 8-4 HBMP7   | 1/2 - 1/4       | 3.88    | 2.70    | 1           | 15,000                  |
| 8-6 HBMP7   | 1/2 - 3/8       | 4.01    | 2.70    | 1           | 15,000                  |
| 8-8 HBMP7   | 1/2             | 4.07    | 2.70    | 1           | 15,000                  |
| 9-4 HBMP7   | 9/16 - 1/4      | 3.95    | 2.70    | 1 1/16      | 15,000                  |
| 9-6 HBMP7   | 9/16 - 3/8      | 4.07    | 2.70    | 1 1/16      | 15,000                  |
| 9-8 HBMP7   | 9/16 - 1/2      | 4.13    | 2.70    | 1 1/16      | 15,000                  |
| 9-9 HBMP7   | 9/16            | 4.20    | 2.70    | 1 1/16      | 15,000                  |
| 12-6 HBMP7  | 3/4 - 3/8       | 4.76    | 3.25    | 1 3/8       | 15,000                  |
| 12-9 HBMP7  | 3/4 - 9/16      | 5.15    | 3.51    | 1 3/8       | 15,000                  |
| 12-12 HBMP7 | 3/4             | 5.08    | 3.31    | 1 3/8       | 15,000                  |
| 16-16 HBMP7 | 1               | 6.52    | 4.25    | 1 3/4       | 12,500                  |